

# Boston Groundwater Trust (BGWT): Inspectional Services Department (ISD) Foundation Data for South End, Roxbury

## Building Underpinned

Cutoff Elev. < 4'

Cutoff Elev.  $\geq$  4'-5'

Cutoff Elev.  $\geq$  5'-6'

Cutoff Elev.  $\geq$  6'-7'

Cutoff Elev. > 7'

Concrete Piles

Wood Pilings

Earth

